Duanesburg Central School District Lead Water Test Results

Sample Number	Location	Source	Initial Test Date	Parts Per Billion	Initial Condition	30 Second Draw Date	30 Secont Draw Result Parts Per Billion	Remediation Plan	Replacement Result	Full Secondary Test Results Date	Secondary Test Date Results per Billion	Result Date	Current Status
1	Room 112	Standard Hand Sink	9/19/2016	4.7	Pass	İ							PASS
2	Room 112	Water Fountain	9/19/2016	17	Failed	10/14/2016	2.8						FAIL
3	Room 112	Toilet Room Sink	9/19/2016	5.2	Pass								PASS
4	Room 111	Toilet Room Sink	9/19/2016	7.6	Pass								PASS
5	Room 111	Drinking Fountain	9/19/2016	6.6	Pass								PASS
6	Room 111	Counter Sink	9/19/2016	4.2	Pass								PASS
7	Room 307	Custodial Slop Sink in closet	9/19/2016	29	Failed	10/14/2016	3.1						FAIL
8	Kitchen	Kitchen Sink	9/19/2016	8.5	Pass								PASS
9	Kitchen	Kitchen Sink	9/19/2016	7.0	Pass								PASS
10	Kitchen	Steam Pot - Sink	9/19/2016	24	Failed	10/14/2016	1.5	Replacement Plan	PASS	2/22/2017	1.6		FAIL
11	Kitchen	Toilet Room Sink	9/19/2016	14	Pass								PASS
12	Kitchen	Diskwasher Spray Hose	9/19/2016	3.1	Pass								PASS
13	Cafeteria	Drinking Fountain	9/19/2016	1.7	Pass								PASS
14	Kitchen	Bathroom Sink & Outside Spigot	9/19/2016	270	Failed	10/14/2016	1.5	Removed Outside Faucet		1			No Existing Unit
15	Room 109	Toilet Room Sink	9/19/2016	3.8	Pass								PASS
16	Hallway near Cafeteria	Bottle Filler	9/19/2016	< 1.0	Pass								PASS
17	Room 117b	Girls Hand Sink in Toilet Room	9/19/2016	1.1	Pass		[PASS
18	Room 117b	Girls Hand Sink in Toilet Room	9/19/2016	< 1.0	Pass	[1]					PASS
19	Room 117b	Girls Hand Sink in Toilet Room	9/19/2016	< 1.0	Pass								PASS
20	Room 117A	Boys Hand Sink in Toilet Room	9/19/2016	< 1.0	Pass								PASS
21	Room 117A	Boys Hand Sink in Toilet Room	9/19/2016	< 1.0	Pass								PASS
22	Room 117A	Boys Hand Sink in Toilet Room near Cafe	9/19/2016	< 1.0	Pass								PASS
23	Room 118	Toilet Room Sink	9/19/2016	1.0	Pass		· · · · · · · · · · · · · · · · · · ·						PASS
24	Room 108	Toilet Room Sink	9/19/2016	1.6	Pass		· · · · · · · · · · · · · · · · · · ·						PASS
25	Room 107 - Room 108 Shared Space	Sink	9/19/2016	25	Failed	10/14/2016	0.86						FAIL
26	Room 107 - Room 108 Shared Space	Sink	9/19/2016	23	Failed	10/14/2016	1.2						FAIL
27	Room 107	Toilet Room Sink	9/19/2016	< 1.0	Pass								PASS
28	119M - Between Rooms 118 and 119	Counter Sink	9/19/2016	13	Pass		1						PASS
29	Room 118 & Room 119 Shared Space	Sink (Nearest Durrant's Room)	9/19/2016	17	Failed	10/14/2016	0.45	Replace Faucet					FAIL
30	Room 119	Sink in Toilet room	9/19/2016	1.6	Pass			·····					PASS
31	Staff Toilet Room	Toilet Room Sink	9/19/2016	2.3	Pass		-	<u></u>					PASS
32	Old Nurses office sink REMOVED	REMOVED	9/19/2016	NA	NA		1						No Existing Unit
33	Room 106 Nurse	Toilet Room Sink	9/19/2016	4.1	Pass								PASS
34	Faculty Room 127	Counter Sink	9/19/2016	8.7	Pass								PASS
35	Custodial Closet	Slop Sink	9/19/2016	44	Failed	10/14/2016	0.08	Replace Faucet and Valves					PASS
36	Room 309 Closet	Sink (Not in use)	9/19/2016	270	Failed		1	Removed Faucet					No Existing Unit
37	Room 309	Sink	9/19/2016	20	Failed	10/14/2016	19.5	Replace Faucet / Abandon Bubbler	POSTED DO NOT DRINK				ABANDONED UNIT - No Existing Unit
38	Room 311	Fountain & Sink Combo	9/19/2016	17	Failed	10/14/2016	4.4	Replace Faucet / Abandon Bubbler	POSTED DO NOT DRINK				PASS
39	Room 312	Fountain & Sink Combo	9/19/2016	20	Failed	10/14/2016	4.3	Replace Faucet / Abandon Bubbler	POSTED DO NOT DRINK				PASS
40	Room 314	Fountain & Sink Combo	9/19/2016	16	Failed	10/14/2016	5.1	Replace Faucet / Abandon Bubbler	POSTED DO NOT DRINK				PASS
41	Room 315	Fountain & Sink Combo	9/19/2016	39	Failed	10/14/2016	3.6	Replace Faucet / Abandon Bubbler	POSTED DO NOT DRINK				PASS
42	Room 316	Water Fountain	9/19/2016	10	Pass								PASS
43	Room 317	Water Fountain	9/19/2016	15	Pass		1	Replace Faucet / Abandon Bubbler	POSTED DO NOT DRINK				PASS
44	Room 128 Staff Toilet Room	Toilet Room Sink	9/19/2016	9.0	Pass	- <u>†</u>	1		1	-			PASS
45	Room 129 Staff Toilet Room	Toilet Room Sink	9/19/2016	10	Pass	<u> </u>	1		İ	1			PASS
46	Room 405	Toilet Room Sink	9/19/2016	8.8	Pass		•						PASS
47	Room 405	Girls Toilet Room Sink	9/19/2016	3.4	Pass	<u>†</u>	1		1	1			PASS
48	Room 405	Girls Toilet Room Sink	9/19/2016	5.7	Pass	- <u>†</u>	1	1	1	1			PASS
49	Custodial Closet	Slop Sink	9/19/2016	4.2	Pass	1	1	1	**	-			PASS
50	Room 401	Toilet Room Sink (Boys)	9/19/2016	3.0	Pass	•	•	<u>+</u>	-	1			PASS
51	Room 401	Toilet Room Sink (Boys)	9/19/2016	3.9	Pass			<u>.</u>					PASS
52	Art Room 402	Counter Sink	9/19/2016	3.2	Pass								PASS
53	Art Room 402	Counter Sink	9/19/2016	4.1	Pass								PASS
54	Room 407	Classroom Counter Sink	9/19/2016	9.8	Pass								PASS
J4			3/13/2010	3.0	1 000		.i	.L			l		1 700

Duanesburg Central School District Lead Water Test Results

Location	Source	Initial Test Date	Parts Per Billion	Initial Condition	30 Second Draw Date	30 Secont Draw Result Parts Per Billion	Remediation Plan	Replacement Result	Full Secondary Test Results Date	Secondary Test Date Results per Billion	Result Date	Current Status
Does Not Exist	NA	9/19/2016	NA	NA								No Existing Unit
Room 403	Counter Sink	9/19/2016	10	Pass								PASS
Room 408b	Sink Only	9/19/2016	420	Failed	10/14/2016	4.6	Replace Faucet / Abandon Bubbler		2/8/2017	15	02/13/2017	PASS
Room 404	Sink	9/19/2016	30	Failed	10/14/2016	4.1	Replace Faucet / Abandon Bubbler		2/8/2017	8.5	02/13/2017	PASS
Room 409	Classroom Counter Sink	9/19/2016	8.9	Pass								PASS
Hallway near 410	Water Fountain	9/19/2016	< 1.0	Pass								PASS
Hallway near 410	Water Fountain	9/19/2016	< 1.0	Pass								PASS
Girls Toilet Room	Toilet Room Sink	9/19/2016	< 1.0	Pass								PASS
Room 415	Toilet Room Sink (Girls)	9/19/2016	< 1.0	Pass								PASS
Room 415	Toilet Room Sink (Girls)	9/19/2016	< 1.0									PASS
Room 417	Toilet Room Sink (Boys)	9/19/2016	< 1.0	Pass								PASS
Room 417	Toilet Room Sink (Boys)	9/19/2016	< 1.0	Pass								PASS
Room 417	Toilet Room Sink (Boys)	9/19/2016	1.4	Pass								PASS
Mop Sink Room 416	Custodial Room	9/19/2016	1.4	Pass								PASS
Room 413	Hand Sink	9/19/2016	< 1.0	Pass								PASS
Room 412	Utility Sink on Counter	9/19/2016	< 1.0	Pass								PASS
Hall 300 Water Fountain	Water Fountain	9/19/2016	43.8	Fail			Replace Fountain and Retest		11/17/2016	1.4		PASS
	Does Not Exist Room 403 Room 404 Room 404 Room 409 Halway near 410 Girls Toilet Room Room 415 Room 417 Room 417 Mop Sink Room 416 Room 413	Does Not Exist NA Room 403 Counter Sink Room 408b Sink Only Room 404 Sink Room 409 Classroom Counter Sink Room 409 Classroom Counter Sink Hallway near 410 Water Fountain Hallway near 410 Water Fountain Girls Toilet Room Toilet Room Sink Gorn 415 Toilet Room Sink (Girls) Room 415 Toilet Room Sink (Girls) Room 417 Toilet Room Sink (Boys) Room 417 Toilet Room Sink (Boys) Room 413 Hand Sink Room 413 Hand Sink	Does Not Exist NA 9/19/2016 Room 403 Counter Sink 9/19/2016 Room 403 Counter Sink 9/19/2016 Room 408b Sink Only 9/19/2016 Room 404 Sink 9/19/2016 Room 409 Classroom Counter Sink 9/19/2016 Hallway near 410 Water Fountain 9/19/2016 Hallway near 410 Water Fountain 9/19/2016 Girls Toilet Room Toilet Room Sink 9/19/2016 Room 415 Toilet Room Sink (Girls) 9/19/2016 Room 415 Toilet Room Sink (Boys) 9/19/2016 Room 417 Toilet Room Sink (Boys) 9/19/2016 Room 417 Toilet Room Sink (Boys) 9/19/2016 Room 417 Toilet Room Sink (Boys) 9/19/2016 Room 417 Toilet Room Sink (Boys) 9/19/2016 Room 413 Hand Sink 9/19/2016 Room 412 Utility Sink on Counter 9/19/2016	Does Not Exist NA 9/19/2016 NA Room 403 Counter Sink 9/19/2016 10 Room 403 Counter Sink 9/19/2016 10 Room 408b Sink Only 9/19/2016 420 Room 404 Sink 9/19/2016 420 Room 404 Sink 9/19/2016 30 Room 409 Classroom Counter Sink 9/19/2016 8.9 Hallway near 410 Water Fountain 9/19/2016 <1.0	Does Not Exist NA 9/19/2016 NA NA Room 403 Counter Sink 9/19/2016 10 Pass Room 403 Counter Sink 9/19/2016 10 Pass Room 408b Sink Only 9/19/2016 420 Failed Room 404 Sink 9/19/2016 30 Failed Room 404 Sink 9/19/2016 8.9 Pass Room 409 Classroom Counter Sink 9/19/2016 <1.0	LocationSourceInitial lest DateParts Per BillionInitial ConditionDateDoes Not ExistNA9/19/2016NANANARoom 403Counter Sink9/19/201610Pass10/14/2016Room 408bSink Only9/19/2016420Failed10/14/2016Room 404Sink9/19/201630Failed10/14/2016Room 404Sink9/19/201630Failed10/14/2016Room 409Classroom Counter Sink9/19/2016<1.0	LocationSourceInitial Test DateParts Per BillionInitial Condition30 Second Draw DateResult Parts Per Does Not ExistNA9/19/2016NANANAImage: Second Draw DateSecond Draw 	LocationSourceInitial Test DateParts Per BillionInitial Condition30 second Draw DateResult Parts Per BillionRemediation PlanDoes Not ExistNA9/19/2016NANA </td <td>LocationSourceInitial Test DateParts Per BillionInitial Condition30' Second Draw DateResult Parts Per BillionRemediation PlanReplacement ResultDoes Not ExistNANANA</td> <td>LocationSourceInitial Test DateParts Per BillionInitial Condition30 Second parts DateResult Parts Per BillionRemediation PlanReplacement ResultPerlacendary Test Results DateDoes Not ExistNA9/19/2016NANAII<</td> <td>LocationSourceInitial Test DateParts Per BillionInitial ConditionJub Second Urag DateResult Parts Per BillionRemediation PlanReplacement ResultProfile Secondary BillionDoes NotExistNA9192016NANABillion<td>LocationNotial Test DateParts Per BellionInitial ConditionSold Scond Drag DateResult Parts Per BellionRemediation PlanReplacement ResultProl Resources Parts Results DateResult Date BullionDoes Not ExistNANAA<t< td=""></t<></td></td>	LocationSourceInitial Test DateParts Per BillionInitial Condition30' Second Draw DateResult Parts Per BillionRemediation PlanReplacement ResultDoes Not ExistNANANA	LocationSourceInitial Test DateParts Per BillionInitial Condition30 Second parts DateResult Parts Per BillionRemediation PlanReplacement ResultPerlacendary Test Results DateDoes Not ExistNA9/19/2016NANAII<	LocationSourceInitial Test DateParts Per BillionInitial ConditionJub Second Urag DateResult Parts Per BillionRemediation PlanReplacement ResultProfile Secondary BillionDoes NotExistNA9192016NANABillion <td>LocationNotial Test DateParts Per BellionInitial ConditionSold Scond Drag DateResult Parts Per BellionRemediation PlanReplacement ResultProl Resources Parts Results DateResult Date BullionDoes Not ExistNANAA<t< td=""></t<></td>	LocationNotial Test DateParts Per BellionInitial ConditionSold Scond Drag DateResult Parts Per BellionRemediation PlanReplacement ResultProl Resources Parts Results DateResult Date BullionDoes Not ExistNANAA <t< td=""></t<>